## CERTIFICATE OF STRUCTURAL SAFETY

[To be jointly signed by an Empanelled Structural Engineer and Owner of the building)]

The following certificate is submitted after site visit and proper investigations for Carmel Convent School, situated at Malcha Marg, ChanakyaPuri, New Delhi-110021.

- Certified that this structural stability certificate has been issued after taking into consideration: (i)
  - (a) The National Building Code of India, including the structural design of foundation, masonry, timber, plain concrete, reinforced concrete, pre-stressed concrete and structural steel shall be carried out in accordance with Part-VI structural design, section-1 loads, section-2 foundation, section-3 wood, section-4 masonry, section-5 concrete and section-6 steel of National Building Code; and
  - (b) All relevant standards prescribed by Bureau of Indian Standards including the standard given in IS-Code 13920-2016, 4326-1993, 13828-1993, 13827-1993, 13935-1993, 456:2000, 800-1984, 801-1975, 875 (Part 2): 1987, 875 (Part 3): 1987, 875 (Part 4): 1987, 875, (Part 5): 1987, 883:1966, 1904:1987, 1905:1987,2911 (Part 1): Section 1: 1979, 1893-2002 for general structural Safety, cyclone/wind protection, earthquake protection. Certified that the above-mentioned building [including tangible items on its rooftops, such as Telecom Tower(s), DG

sets, water storage capacity, Air sconditioning	units, etc.] existing as on date, fulfils all the structural safety
requirements.	, and an area and survey
SIGNED BY: (* New Delhi) *	COUNTER SIGNED BY:
Signature of Structural Engineer Name of Structural Enga Naveen Joith	Signature of Owner(s):
The state of the s	Name of Owner(S): SR. SUMLTA
Address of Structural Engg.: E-60, 2nd Floor,	
Masjid Moth, Greater Kailash- III, New Delhi- 110048	Address Of Owner(S): CARMEL CONVENT
Date 02/11/2020	Date 02/11/2020 MALCHA MARG, CHANAKYAPI
	Manager Delhi - 11002

MCD LIC NO: SE/0416

(ii)

New Delhi-110021 In addition to the certification given at Sl.No. (i) And (ii) above, it is also certified that:

- Any tangible item on the rooftop of the above-mentioned building (as existing as on date), such as Telecom Tower(s), (iii) DG sets, Water storage capacity, Air conditioning units, etc., are in accordance with the necessary permissions / clearances etc.
- The owner(s) of the above-mentioned building undertakes that they shall be liable for all criminal and/or civil (iv) liability(s) arising out of non-adherence to the statutory compliances, including structural safety of the building.

SIGNED BY	
Signature of Owner(s):	
Name of the Owner(s): SR. SUMITA	
Address of Owner(s): CARMEL CONVENT MAICHA MARG	
Address of Owner(s): CARMEL CONVENT, MALCHA MARG Date 02/11/2020 CHANAKYAPURI, NEW DELHI-	11002
Manager	

Carmel Convent School New Delhi-110021

Carmel Convent School New Delhi-110021

Carmel Convent School