

## Building safety Certificate

No. 1.2/B/2023

I Prabhakar Tiwari ..... (Registered Structural Engineer Nagar Nigam Singrauli) visited the Christ Jyoti School Situated at Singrauli, Morwa on ..... 04.04.2023 ..... with the authority and certified the building safety norms follows as below.

1.0 That all Buildings blocks are conventionally R.C.C Structure, R.C.C frame structure and are sound enough to bear the load of students and if used for public function utility. All structures are on column footing foundation & R.C.C Column with roof beam & slab.

The residual life of every building is more than 40 years,

Also there is no temporary structure adjoining to building and also in school premises. There is no crack or damage found in any building structure.

All the construction are complete, the construction of building is as per sanction made from Nagar Nigam Singrauli (Local Govt. Authority) stair case are provided at all junctions of building and end of building for proper circulation.

Building is well ventilated & gets natural light from all around.


2.0 All the electric fittings & line are with conduit pipes & are at adequate height.


The D G set is covered by Grill & is away from reach of children.

3.0 To prevent from the hazards adequate nos. of fire fighting instruments are provided as per norms, special security is done for labs. The circulation area and open space is left around each building for free movement of fire fighting vehicles. There is no sump well or open tank at ground and in any floor of building.

4.0 The play ground is well maintained & is also surrounded by boundary wall of good height.

Here by this is certified that all the above mentioned building fulfills all the safety norms and is suitable to be utilized for the students.

  
Manager  
Christ Jyoti Sr. Sec. School  
P.B. No. 53  
Singrauli Colliery P.O.  
Distt. Singrauli (M.P.) 486889

  
उपकार यंत्री  
नं० ५० नि० सिंगरौली  
उपकार्यालय मोरवा